

WPCSF 9.1 VI

MR. DANFORTH BODIEN
Toxic Substances Control Branch
M/S 524, U.S. E.P.A.
1200 Sixth Ave.
Seattle, Wa. 98101

JUN 2 0 1983

COMPLIANCE SHANCH EPA - REGION X

Mr. Bodien.

In response to your letter of May 19th, 1983 please find the following information you requested.

The only substance delivered to Western Processing for us would be our spent Pickle Liquor. This consists of appx. Seventy percent Water, Ten percent Sulphuric Acid, Ten percent Iron sulphate, & Ten percent Zinc sulphate.

In 1979 we had appx. 32.4 tons delivered to Western Processing. This consists of appx.: 22.68 Tons of Water

3.24 Tons of Sulphuic Acid

3.24 Tons of Iron Sulphate

3.24 Tons of Zinc Sulphate

For 1980 there was appx. 150.48 Tons consisting of Appx. :

105.336 Tons of Water

15.048 Tons of Sulphuric Acid

15,048 Tons of Iron Sulphate

15.048 Tons of Zinc Sulphate

In 1981 there was appx. 97.56 Tons consisting of appx.:

77.292 Tons of Water

9.756 Tons of Sulphuric Acid

9.756 Tons of Iron Sulphate

9.756 Tons of Zinc Sulphate

All our material was transported for us via Tanker Truck.

From 1979 thru 1981, our material was transported by Liquid Waste Disposal. Their address is:

P.O. Box 3821 Seattle, Wa. 98124

From 1982 to 1983, our material was transported via N.W. Tank Service. Their address is:

USEPA SF 1473559

GALVANIZERS OF STEEL SHIPS BJET PLANES BBRIDGES BSUBMARINES BFLAGPOLES BNUTS



1500 Airport Way So. Seattle, Wa. 98134

We have hazardous waste manifests for all our material transported from our facility to Western Processing. Our transporters also have copy's of these manifests at their facilitys.

According to Garmt Neuienhauser, all of our material was reprocessed in Western Processing's fertilizer process and therefore we should not have any material left at Western Processing.

If you have any other questions, please feel free to contact us at any time.

matriyou,

Gerald Armstrong
Vice-President

dkk